

AS-BUILT REPAIR QU	JANTITY	TABLE
TOP OF DECK REPAIRS		
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	760 SQ. YDS.	
CLASS II SURFACE PREPARATION	0.0 SQ. YDS.	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.0 SQ. YDS.	
SHOTBLASTING BRIDGE DECK	760 SQ. YDS.	
PPC MATERIALS	26.4 CU. YDS.	
PLACING AND FINISHING PPC OVERLAY	760 SQ. YDS.	
GROOVING BRIDGE FLOORS	6,228 SQ.FT.	

TOP OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR FOR PPC OVERLAY AFTER REMOVAL OF UNSOUND CONCRETE. (MIN. 2"CLEAR TO SAWCUT). SEE OVERLAY SURFACE PREPARATION FOR POLYESTER POLYMER CONCRETE SPECIAL PROVISION.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE. FOR SECTION A-A AND SECTION B-B, SEE "JOINT DETAILS" SHEET.

APPROX. CLASS II SURFACE PREPARATION

PROJECT NO. 15BPR.18 DAVIE COUNTY 63 BRIDGE NO.:___

SHEET 4 OF 4

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

PLAN OF SPANS

I, J &

APPROACH SLAB

SHEET NO S-7

TOTAL SHEETS

DATE:

Krishna P. Sedai SEAL 031583 7/25/2018

REVISIONS NO. BY: DATE: DOCUMENT NOT CONSIDERED -FINAL UNLESS ALL SIGNATURES COMPLETED

H.A. LOCKLEAR _ DATE : <u>3/18</u> DRAWN BY : _ M.G. SHAIKH _ DATE : ____5/18 CHECKED BY : __